



Voltmeter and Load Control Tutorial


Step 1. Power the Flexs Q4 by connecting the supply terminal to a dc power source.



Step 2. To measure battery voltage, connect the positive battery terminal to one of the analog input channels as shown.



Step 3. To switch a light on and off, route it's supply through one of the onboard load switches as shown.



Step 4. Open the devices onboard webserver and click on the "Registers" tab, from there you can view the battery voltage and toggle the load switch.

